

## Therma Hygrometer and Thermometer



[Click here to view product](#)

<b>Product Code</b>	XE-3985-001
<b>General Description</b>	The 6500 therma-hygrometer incorporates a clear custom LCD with °C, %rh, max/min, hold and dew point indication. An auto power-off facility turns the instrument off after 10 minutes? non-use.
<b>Accuracy</b>	Temperature: $\pm 1$ °C over the range 5 to 45 °C otherwise $\pm 1.7$ °C Humidity: $\pm 3\%$ (20 to 80 %rh)
<b>Resolution</b>	Temperature: 0.1°C/°F Humidity: 0.1%rh
<b>Dimensions</b>	25 x 56 x 128mm
<b>Max. Temperature</b>	70°C

<b>Min. Temperature</b>	-20°C
<b>Weight</b>	160 grams
<b>Power Supply</b>	3 x 1.5-volt AAA. Battery life: 10000 hours
<b>Sensor Type</b>	temperature: silicone bandgap ? humidity: capacitance polymer